


Programmable Electronic Weight Indicator NSHF

Features:

- ◆ **A/D Input:**
 - High technology conversion (Σ - Δ)
 - External resolution 1/40000
 - Up to 8 - 350 ohms or 16 - 700 ohms load cells
 - Load cell excitation 5Vdc (Σ - Δ)150 mA Max.)
- ◆ **Power Supply:**
 - Internal battery charger:
Input 120Vac 60Hz 0.5A
 - Rechargeable sealed battery
6Vdc 1.2Ah
- ◆ **Enclosure:**
 - Stainless Steel housing.
- ◆ **Multi-weighing units:**
 - kg, lb & 2 customized Units
- ◆ **Display:**
 - 6 Digits, 7 segments red LED
 - 1" High digits
 - +9 Indicators LED
- ◆ **Interface:**
 - RS232
 - Configurable rates from 1200 to 19200 bps
- ◆ **Zero set:**
 - Configurable range
 - Automatic & Manual operation
- ◆ **Options:**
 - Wireless RS232 transmitter
 - Virtual remote display though network
 - Remote display (3" & 5" digits high)
 - Relay outputs module for over-OK-under signals




Typical Applications:

- ◆ Receipt & Shipping scales
- ◆ Counting parts scales
- ◆ Over-OK-Under scales
- ◆ Pick & Hold scales
- ◆ Accumulator weight scales
- ◆ Livestock scales
- ◆ Bench scales
- ◆ Floor scales

Programmable Electronic Weight Indicator NSGP

Features:

- ◆ **A/D Input:**
 - High technology conversion (Σ - Δ)
 - External resolution 1/40000
 - Up to 8 - 350 ohms or 16 - 700 ohms load cells
 - Load cell excitation 5Vdc (150 mA Max.)
- ◆ **Power Supply:**
 - Internal battery charger:
Input 120 Vac 60 Hz 0.5 A
 - Rechargeable sealed battery
6Vdc 1.2Ah
- ◆ **Enclosure:**
 - Plastic ABS housing.
- ◆ **Multi-weighing units:**
 - kg, lb & 2 customized Units
- ◆ **Display:**
 - 6 Digits, 7 segments red LED
 - 1" High digits
 - +9 Indicators LED
- ◆ **Interface:**
 - RS232
 - Configurable rates from 1200 to 19200 bps
- ◆ **Zero set:**
 - Configurable range
 - Automatic & Manual operation
- ◆ **Options:**
 - Wireless RS232 transmitter
 - Virtual remote display though network
 - Remote display (3" & 5" digits high)
 - Relay outputs module for over-OK-under signals



Typical Applications:

- ◆ Receipt & Shipping scales
- ◆ Counting parts scales
- ◆ Over-OK-Under scales
- ◆ Pick & Hold scales
- ◆ Accumulator weight scales
- ◆ Bench scales
- ◆ Floor scales